




360 degree camera without blind spot




Any other method yields blind spots



Using whole area of the sensor, but there are blind spots in four directions.
(Company A)



Using the sensor area effectively, but there are blind spots in two directions.
(Company M)



Using specially designed lens with the mirror is evaporated inside, there is a blind spot in the center of view. (Company T)